

#### **a. Email received from ROSPA ahead of play safety report**

Please see below the details of the High Risk Findings, found at the site, School Lane, Hadlow Down:

##### **Asset - Multiplay**

##### **Finding Details**

Risk Score: 13 (High)

Name: Timber - decay, Timber is decayed.

Notes: Slides support is decayed. Replace.

Please note, this is an immediate bulletin generated automatically once an inspector has synchronised his or her report. The full report will follow in due course, after undergoing checking.



#### **b. New School Lane Sub-Station**

Hi all,

It is my understanding that UK Power Networks are planning to replace the old existing sub-station in School Lane in the relatively near future. Work has been done to ensure continued supply whilst this work takes place via rerouting the power. I do not have timescales.

Best Wishes